

GOVERNMENT OF TELANGANA
ROADS AND BUILDINGS DEPARTMENT

From,
Sri. B. Lal Singh, B.E,
District (R&B) Officer,
Division : Vikarabad

To,
The Principal,
Hyderabad Institute of Excellence School,
Vikarabad District.

Letter No : EE/DB/T3/VKB/Structural Stability/School/2021-22 Date: 22 .07.2021

Sub: (R&B) Dept – Hyderabad Institute of Excellence School- Sy. No.195, 196,197/P at
Madgula Chittempally Village, Vikarabad Municipality, in Vikarabad District, –
Structural and Soundness Certificate – Inspection Report Submitted - Reg.,

Ref 1 : EE (R&B) Vikarabad DB/T3/Soundness/2021-22, Dt: .5.2021

2. Lr.No. DEE/VKB/Structural Stability/School/2021-22 Dt: 22.07.2021


Adverting to the subject cited above and vide reference cited 2nd above, I am to submit that the Deputy Executive Engineer (R&B) Sub Division, Vikarabad has reported that the inspection was done for the School building on 12-7-2021 having Sy.No.195,196,197/P at Madgula Chittempally Village, Vikarabad Mandal & District. It is observed that the RCC building with G+2 framed Structure was already constructed. The walls in Ground floor, 1st floor & 2nd floor are completed. The applicant is running the School. This building construction was completed in the year 2015-16 as certified by the Structural Engineer and Owner of the building.

The School Building inspection was done superficially and observed the following points and instructed to attend the some issues immediately.


1. The old impervious coat over 2nd floor Slab was dismantled and instructed to provide impervious coat on roof surface.
2. Slab leakages are observed in 2nd floor and should be rectified.
3. Repairs to the expansion joint should be attended.

It is also submitted that Smt .G.Nagamma, M.Tech, Satya Constructions, Vikarabad has certified that the school building was constructed and completed under her close supervision and executed the work as per NBC and IS Code standards and informed that the building is structurally safe.

For Hyderabad Institute of Excellence


Principal

For Hyderabad Institute of Excellence


Secretary

In view of the above, the School building is superficially inspected and sounds to be good in condition and fit for occupation and running the school based on the structural engineer report. The issues mentioned above should be attended without delay and before start of the classes. Any further building structural issues comes up, after issuing the structural soundness permission from the (R&B) department, the Owner / School Management should be attended immediately and also instructed to do the regular maintenance.

In view of the above, the permission for fitness certificate accorded for the School building for the period of One Year i.e from 26.07.2021 to 25.07.2022.

This is for favour of information and further necessary action.

Yours Faithfully,


District (R&B) Officer,

(Executive Engineer),
Division : Vikarabad.





For Hyderabad Institute of Excellence Junior College


Principal

For Hyderabad Institute of Excellence


Secretary